

PIX Pentagon ® Poly-V Belts Wear Gauge

PVPENTAGON



Cutting range:

Now you can inspect the Poly-V Belts, using "PIX-Pentagon", a composite Poly-V Belt wear-measurement gauge, which can check the wear of the ribs and the thickness of all Poly-V Belt sections.

If you would require any additional information, please write an e-mail to us at info@pixtrans.com