

PIX-Belt Length Measurer

TLMLMZZZZ004

PIX Belt length measure is useful in knowing the length of the Belt, where the size on the Belt is not visible.



They are available in two variants -

- Flat-pulley length measure: It is the universal tool to measure the length of almost all kinds of Belts, it facilitates measurement of Belt-length irrespective of its groove angle. Can be used to measure Belts up to 120 inches.
- V-groove pulley length measure: It is used to measure the length of the conventional Belts and the Poly-V Belts up to 120 inches.

If you would require any additional information, please write an e-mail to us at info@pixtrans.com